RAND McNALLY

Rand McNally Device Software

What's New (Version 5.20)

Rand McNally Device Software – Release Notes (Version 5.20)

What's New	Description	How to Access
HOS		
Intrastate HOS rules for CA, TX, FL*	When configured in the Connect web portal, the in-cab device will calculate Hours of Service timers according to intrastate Hours of Service rules for California, Texas and Florida.	HOS
California Agricultural exemptions*	When configured in the Connect web portal, the in-cab device will calculate Hours of Service timers according to California Agricultural Hours of Service exemptions.	HOS
Cycle 1 Canadian HOS rules (For US drivers traveling in Canada)*	When configured in the Connect web portal, the in-cab device will calculate Hours of Service timers according to Canadian Hours of Service rules for US drivers traveling in Canada.	HOS
Motor coach HOS rules*	When configured in the Connect web portal, the in-cab device will calculate Hours of Service timers according to motor coach Hours of Service rules.	HOS
Setting to eliminate the driver's ability to reject the 34-hour reset*	When configured in the Connect web portal, the in-cab device will eliminate the driver's ability to reject the 34-hour reset.	HOS

* Requires Connect web portal update 1.0.6.0 (FleetWatcher update 4.00)

Rand McNally Device Software – Release Notes (Version 5.20)

What's New	Description	How to Access
IntelliRoute®		
IntelliRoute® 3.5 software	IntelliRoute® 3.5 software update includes: • Award-winning truck-specific maps and routing – an updated road network with truck navigation incorporating legal and physical restrictions plus page-and-grid references to Rand McNally's 2014 *Motor Carriers' Road Atlas.* • Compare Routes – Provides a primary route and a reasonable alternate, allowing the driver to choose. Both routes are presented on a map for a quick review. • Speed limit updates across the U.S. and Canada • 52,000 changes that impact routing including vertical clearance and weight restriction updates, number of axels permitted, and low ground clearance railroad crossings ("Hump" RR crossings). • Over 2,000 truck-relevant points of interest updates such as weigh stations, rest areas/welcome centers, and truck friendly hotels, including the addition of 157 rest areas, and 77 CAT Scales. • Updates to emergency contact phone number and truck trailer length information by state.	IntelliRoute®

What's New	Description	How to Access
Other		
Capture vehicle VIN via J1708*	The in-cab device's VIN is now visible via J1708 protocol in the Connect web portal.	N/A (no driver interaction needed)
Wi-Fi support for non-broadcast SSIDs*	The new Wi-Fi support for non-broadcast SSIDs means in-cab devices can now connect to secure, hidden access points.	N/A (no driver interaction needed)

* Requires Connect web portal update 1.0.6.0 (FleetWatcher update 4.00)

RAND MCNALLY   **Rand McNally Device Software – Release Notes (Version 5.20)**

Improvements:

- The Search field in the Library on TPC 7600 in-cab devices now features a button to clear the field.